Indzawo Optic Connect

Relay protection time synchronization abnormality





© 2026 Indzawo Optic Connect - All rights reserved

Relay protection time synchronization abnormality



Within the DPU/TPU, there is a time clock, which may be enabled or disabled. If the clock is disabled, then the relay will not time stamp each event in the relay. If the clock is enabled, then the user may ...



Data communications between protection relays and the SCADA system have no influence on the accuracy of time synchronisation. Separate systems increase the cost of construction through extra ...



This paper discusses implementing PTP master-clock functionality in protection relays and how it simplifies the substation protection-and-control architecture and increases reliability and availability of ...



In this paper, the cause of the starting delays of protective relays is analyzed through assumptions and approximations. On this basis, an adaptive current differential protection method for ...



Improper synchronization of electrical sources can have damaging effects on a power distribution system, resulting in electrical and mechanical transients that can destroy prime movers, ...

© 2026 Indzawo Optic Connect - All rights reserved




The network infrastructure components (e.G. network switches) participate in the time synchronization Much more configuration options compared to NTP Profiles define subsets of those options for ...



In this paper, the effect of time synchronization error on protection algorithms are studied for the usage of the LAN-based collaborative protection.



IEC 61850-5 standard defines the time requirements for latency in protection systems as the transfer time . Table IV lists the transfer time requirements for protection and control applications.



This pilot project shows a simple and cost effective way to retrofit already installed protection relays independently of the time synchronization method required by these devices.



Properly time-synchronized data facilitates the identification and understanding of the sequence of events prior to, during and after the disturbance and is particularly valuable when analyzing data ...



In this paper, test results are presented that demonstrate the impact of time inaccuracy on synchrophasors, TWFL and 87L functions during clock holdover state. The importance of installing ...

© 2026 Indzawo Optic Connect - All rights reserved

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: https://www.indzawo.co.za
Email: sales@indzawo.co.za
Phone: +27 71 296 8473
Address: 22 Quantum Street, Midrand, 1685, Gauteng, South Africa

This document is for informational purposes only. Specifications subject to change without notice.

© 2026 Indzawo Optic Connect - All rights reserved