1 meter of outer sheath stripped from 8-core optical cable





© 2026 Indzawo Optic Connect - All rights reserved


1 meter of outer sheath stripped from 8-core optical cable

	The round blade is used for stripping the outer sheath, and the flat blade is used for stripping the core wire. The blade holder automatically shifts to switch the appropriate blade.
	Good fiber optic stripping techniques in your cable assembly process are crucial. See best practices for how to strip fiber optic cable buffers & jackets.
	From removing the outer jacket to cleaning the bare fiber and achieving a perfect cleave, each stage demands attention to detail and the use of specialized tools. In this guide, we''ll walk you ...
	This best practices document is a step-by-step guide for end and midspan access of loose tube optical cable, including sheath removal, core preparation, and fiber preparation.
	Sheath is another name for this flexible insulating material, which is usually made of soft plastic. OD is normally 2-3mm in diameter on single-fiber cables (as shown above) and can be ...

© 2026 Indzawo Optic Connect - All rights reserved



In this lesson, we will identify and examine cables, then prepare them for splicing or termintion by stripping the cable to expose the coated fibers. Finally we will strip fibers, the final step before ...



Do not crush the cable or allow it to kink. Doing so may cause damage that can alter the transmission characteristics of the cable - the cable may have to be replaced.



The purpose of fiber optic cable strippers is to remove any plastic protective coatings from the fiber optical strand assembly prior to cleaving, ...



Strip back and remove the 7-in. to 10-in. long piece of outer jacket to expose the ripcord, which you''ll use to remove the rest of the jacket to the Step 1 mark.




Good fiber optic stripping techniques in your cable assembly process are crucial. See best practices for how to strip fiber optic cable buffers & jackets.



These fiber buffer stripping tools provide a quick, easy, and reliable way to remove the buffer from an optical fiber in preparation for connectorization. A fiber guide and matched blades ensure that the ...

© 2026 Indzawo Optic Connect - All rights reserved

	In this informative guide, we''ll walk you through the step-by-step ...
	In this informative guide, we''ll walk you through the step-by-step process of stripping and preparing fibre optic cable for termination, covering techniques, tools, and best practices to help you ...

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: https://www.indzawo.co.za
Email: sales@indzawo.co.za
Phone: +27 71 296 8473
Address: 22 Quantum Street, Midrand, 1685, Gauteng, South Africa

This document is for informational purposes only. Specifications subject to change without notice.

© 2026 Indzawo Optic Connect - All rights reserved